

## VENTURI BULLET FITTING \_ STELLAR SKIS

Can you send give me some instructions on fitting the bullets to an early model SES (it is one of the first ones that came out with the tight bucket). The venturi appears to be bigger and the bullet goes all the way in - where is its optimum placement?

OK

- Assume it is the old SE that has a dent in the hull at the opening of the venturi
- To be really effective this whole indent needs to be filled ensuing the opening remains clear
- The Bullet sits 2mm (no more) away from the bullet – will attach photo
- The rounding of the hull after filling the indent makes the bullet sit ideally

Realise this is a bit of work but you can't fit if the dent is not filled.

